बीएचईएल स्ट्रिस

PRODUCT STANDARD

SWITCHGEAR ENGINEERING DIVISION SG 16014 Rev 00

Page 1 of 2

GEAR BOX FOR MOTORISED ISOLATOR IN 36KV GIS

1. APPLICATION:

A gearbox with a worm and worm wheel arrangement is required for driving the moving contacts of switchgear. This gearbox will be used with a fractional HP motor directly mounted on the gearbox. The output shaft rotates at a slow speed and provides sectorial movement of $<\!360^{\circ}$. The limits are controlled, electrically, by limit switches. The assembly is engaged to the load by means of splines provided in the worm wheel.

2. GEAR BOX SPECIFICATIONS:

2.1 Output : Spline as per details in fig.03

2.2 Input shaft diameter : To suit motor-drive (ϕ 12)

2.3 Size : 110x115x90mm, refer OGA No.GB-00

2.4 Ratio : 25:1

2.5 Body : Aluminum Alloy(Cast)

2.6 Worm : Ferrous(EN-24), ground and polished

2.7 Wheel : Ferrous/Non-Ferrous

2.8 Bearings : Needle/Ball

2.9 Lubrication : Grease/Oil

2.10 Sealing : Neoprene oil seals at shaft

2.11 Manual operation: A square recess (16 A/F, 16mm deep) shall be provided to manually operate the gear.

3. GENERAL:

The information on this document is the property of Bharat Heavy Electricals Limited It must not be used directly or indirectly in any way detrimental to interest of Co.

COPYRIGHT AND CONFIDENTIAL

- 3.1 S.S. threads shall be used in all tapped holes.
- 3.2 Refer Fig.1 for Motor details.
- 3.3 Refer Fig.2 for Motor mounting details.
- 3.4 Refer Fig.3 for spline details.

REV.	PRINTS TO:-		APPROVED -		
ALTD.	Issued online		HRP		
APPD.			PREPARED	ISSUED	DATE
DATE.			Sonali Sinha	VKD	24.7.14

PRODUCT STANDARD SG16014 Rev 00					
SWITCHGEAR ENGINEERING DIVISION Page 2 of 2					
4. SURFACE FINISH: a) Process: Powder coating b) Color: Black c) Finish: Structure(dull) Note: The gearbox shall be sand blasted, deburred and degreased before powder coating with black Nylon powder. 5. TEST CERTIFICATE: The gear box shall be subjected to a load-cycling test. Load-cycle is defined as operation of the gear from rest to 350° clock wise and return to original position 350° counter clock wise. 1000 No-load operations and 200 On-load operations shall be carried out during inspection. The gear box shall be inspected for wear and tear of the parts. Heavy wear shall reject the supply. Fig01:Motor Detail					
Fig02:Motor Mounting Detail					
#0.02 #0.02 #0.02 #0.02 #0.02					
Fig03:Spline Details					