



- NOTES:-
1. FAN MUST BE STATICALLY BALANCED WITHIN 200 GRAMS AFTER MACHINING.
 2. DYNAMIC BALANCING SHOULD BE DONE BY WELDING BALANCE WEIGHT (ITEM 002) WEIGHT TO BE DONE TO REMOVE BURR & SPARK.
 3. EACH COMPONENT SHALL BE LEGIBLY MARKED WITH THE FOLLOWING INFORMATION BY MACHINING SUPPLIER:
 - a) SUPPLIER'S NAME.
 - b) DRAWING NO.
 - c) BHEL PO NO UNDER A SHOP IDENTIFICATION CODE.
 - d) MONTH & YEAR OF FINAL MACHINING.

REV	DATE	BY	CHKD	REASON
001				
002				

NO.	DESCRIPTION	DATE	BY	CHKD
001	BALANCE WT			
002	FAN (S/N/CO)			

NO.	DESCRIPTION	DATE	BY	CHKD
001	FAN (S/N/CO)			

REV	DATE	BY	CHKD	REASON
001				
002				

INVENTORY NO.	SIGN. & DATE	REF. DRG. NO.

REV	DATE	BY	CHKD	REASON
001				
002				

NO.	DESCRIPTION	DATE	BY	CHKD
001	FAN (S/N/CO)			

NO.	DESCRIPTION	DATE	BY	CHKD
001	BALANCE WT			
002	FAN (S/N/CO)			

NO.	DESCRIPTION	DATE	BY	CHKD
001	FAN (S/N/CO)			